| Product name | Recycling passport Mammotrak trolley 1.5T and 3.0T | | | | |
|------------------------|--|--|--|--|--|
| Identification code(s) | 98960301987x (1.5T version) and 98960302084x (3.0T version) (where x can be any digit from 19) | | | | |
| Total weight [kg] | 142 kg | | | | |
| Manufacturer | Philips Healthcare Nederland B.V. | | | | |
| Address | Veenpluis 4-6 Best | | | | |
| Zip code | 5684PC | | | | |
| Country | The Netherlands | | | | |
| Electronic info | APT591-08-4701 Mammotrak excl RF coils WEEE passport | | | | |

Recycling information

| Special Attention |
|--------------------------|
| A |
| |
| |

| Items | Location |
|---|--|
| Under the carrier in the spacer there is a cable slab. An RF cable, a nurse call cable, and the headset tube run through this cable slab. | Nr 1: Figure 2 |
| An ODU connector (for the RF cable) and connectors for the nurse call and headset are positioned under the lid at the head-end of the carrier | Nr 2: Fig 1 and fig 4 |
| A cable plus ODU connector and connection to the headset and nurse call are at the side of the spacer. | Nr 3: Fig 3 and 4 ODU Connector: fig 5. |

| Batteries |
|-----------|
| |
| × |
| 0 |
| |


| Items, type | Location |
|----------------|----------|
| Not applicable | |
| | |
| | |

| Hazardous substances |
|----------------------|
| \wedge |
| |
| |
| |

| ; | Items | Location |
|---|---|----------|
| | Beryllium copper contact pins on ODU connectors | Fig 5 |
| | | |

| | | | | 98960301 and 9896030 | ` | , | Version: 00 Doc.Date: 2008-10-15 | <u> </u> |
|---------|--|--|----------------------------|-------------------------|------------|---|--|----------|
| Author: | | | Pag.: 1 of 4 | Group No: 5790 | Section: - | | Status: Authorized | |

| Fluids and gases | Items | Location |
|------------------|----------------|----------|
| | Not applicable | |
| | | |



| Name: Recycling Passport Mai | olley 1.5T | 98960301 and 9896030 | ` | , | Version: 00 Doc.Date: 2008-10-15 | 5 | | |
|---------------------------------|------------|-------------------------|----------------------------|----------------|--|---|--------------------|--|
| Author: | | | Pag.: 2 of 4 | Group No: 5790 | Section: - | | Status: Authorized | |

Nr 1: Cable slab, containing RF cable, nurse call cable and tube for headset




Fig 2: Artist Impression of Mammotrak docked to the MR scanner




Fig 3: Mammotrak without carrier

| Recycling Passport Mai | 98960301 and 9896030 | ` | , | Version: 00 Doc.Date: 2008-10-15 | j | | | |
|------------------------|-------------------------|---|----------------------------|--|------------|--|--------------------|--|
| Author: | | | Pag.: 3 of 4 | Group No: 5790 | Section: - | | Status: Authorized | |




Fig 4: Mammotrak with headset and Invivo RF coil




Fig 5: Layout of ODU connector

| Name: Recycling Passport Mammotrak trolley 1.5T and 3T | | | | 9896030 and 9896030 | ` | , | Version: 00 Doc.Date: 2008-10-15 | j |
|--|--|--|----------------------------|------------------------|------------|---|--|---|
| Author: | | | Pag.: 4 of 4 | Group No: 5790 | Section: - | | Status: Authorized | |