





PHILIPS HEALTHCARE	Product Recycling Passport	Page 1 of 3
-------------------------------	-----------------------------------	-------------

Product name:	Sparq Medical Diagnostic Ultrasound Equipment	
Identification code(s)	989605394911	
Total weight (in Kg)	71.13 kg	
Producer/ Manufacturer	Name company:	Philips Ultrasound
	Address:	22100 Bothell Everett Highway, Bothell, WA
	Zip code:	98012
	Country:	USA

Recycle Info	Items:	Location
Special attention 	Arm gas strut under pressure	Figure 1 [1]
	Vertical articulation gas strut under pressure	Figure 1 [3]

	Items:	Location
 Fluids / Gases	Oil and Nitrogen gas: in gas strut in Articulation Arm mechanism. Do not drain oil with device under pressure	Figure 1 [1]
	Oil and Nitrogen gas: in gas strut in vertical articulation mechanism. Do not drain oil with device under pressure	Figure 1 [3]

	Type:	Location
Batteries  To be Removed	Battery in System. Button cell on Mainboard.	Figure 1 [4]
	Battery in System. Four (x4) LiON Batteries in the Power System	Figure 1 [5]

	Substances:	Location
Hazardous  To be Removed	Mercury (Hg) – Monitor contains mercury in the backlight lamps.	Figure 1 [2]
	Lead (Pb) -- Contains lead in PCB's and solder.	Figure 1 [6]

Show locations of materials mentioned on the previous sheet. (Picture information)




Figure 1: Sparq

Recycling Passport Revision History

Rev	Description	Date
A	First Passport	April 5 , 2013