

Product Recycling Passport

Page **1** of **9**

Product name		Ingenuity CT Gantry	
Identification code(s)		459800708861	
Total weight (in Kg)		1941	
Producer/ Manufacturer	Name company:		Philips Medical Systems
Add		ress:	595 Miner Road Highland Heights, Ohio
	Zip	ode:	44143
	Cou	ntry:	United States of America

Recycle Info	Items:	Location
	Spring loaded cover	Figure 1 (1)
Special attention	Actuators: Unstable when removed, possible rotation of frame	Figure 4 (2), Figure 5 (2)
	System Unbalanced when rotor components are removed	Figure 3 (5)
	causing rotation	
	Printed Circuit Boards	Figure 1 (2), Figure 2 (1),
السمعة		Figure 4 (1),
		Figure 5 (1),
		Figure 6 (2)
	Items:	Location
	X-Ray Tube Hydrocarbon Oil	Figure 3 (2)
	Generators Hydrocarbon Oil	Figure 3 (6)
	Overflow Tank Hydrocarbon Oil	Figure 3 (7)
	Radiator Hydrocarbon Oil	Figure 3 (9)
	Gas Springs	Figure 3 (10)
Fluids / Gases		
	Type:	Location
Batteries	Lithium Ion (in Rhost PCB)	Figure 3 (8)
	Lithium poly-carbon monofluoride	Figure 6 (3)
To be Removed		

PHILIPS
HEALTHCARE

Product Recycling Passport

Page **2** of **9**

	Substances:	Location
Hazardous	Contains Hexavalent Chromium (Optical Ring)	Figure 6 (1)
^	Found in systems with manufacturing date before August 2015	
	Contains Lead (Pb) Components	Figure 3 (1),(3),(4)
To be Removed		

Locations of materials mentioned on the previous sheet(s). (Picture information)




Figure 1: Front View of Gantry with Covers on




FIGURE 2: REAR VIEW OF GANTRY WITH COVERS ON




Figure 3: Front View of Gantry with Front Cover Lifted




Figure 4: Right Side View of Gantry with Cover Removed




Figure 5: Left Side View of Gantry with Cover Removed




Figure 6: Back View of Gantry with Cover Removed

PHILIPS HEALTHCARE	Product Recycling Passport	Page 9 of 9

Recycling Passport Revision History

Rev	Description	Date
00	Ingenuity CT Recycling Passport	11-Nov-2015