
PHILIPS
HEALTHCARE

Product name:		Brillian	ce iCT Patient Support	
Identification code(s)		4535 674 80181		
Total weight (in Kg)		395		
Producer/	Name c	company:	Philips Medical Systems	
Manufacturer	Address:		595 Miner Road Highland Heights, Ohio	
	Zip code:		44143	
	Country:		United States of America	

Recycle Info	Items:	Location
Special attention	Removal of Motor: Couch will drop when motor is removed.	Figure 1 (1)
	Green Safety Block: When removed, couch may collapse.	Figure 1 (3)
	Giant Spring: Potential energy hazard.	Figure 1 (4)
Fluids / Gases	Items:	Location
Batteries	Туре:	Location
To be Removed		
Hazardous	Substances:	Location
A	Printed Circuit Boards	Figure 1 & 2 (2)
To be Removed		

Show locations of materials mentioned on the previous sheet. (Picture information)



(2)






Figure 3: Full view of Patient Support

Recycling Passport Revision History

Rev	Description	Date
A	CO 2019848-Release Status A	24 February 2009
В	CO 2020759 - Removed superfluous header, added whole patient support picture and corrected Rev A description to be "CO 2019848"	09 June 2009