| Product name: In | | Ingenui | ngenuity CT Gantry | |
|-------------------------------|-------------------|--------------|---|--|
| Identification code(s) | | 459800029801 | | |
| Total weight (in Kg) | | 1941 | | |
| Producer/ | Name company: | | Philips Medical Systems | |
| Manufacturer | Addres Zip cod | | 595 Miner Road Highland Heights, Ohio 44143 | |
| | Country: | | United States of America | |

| Recycle Info | Items: | Location |
|-------------------|--|--|
| Special attention | Spring loaded cover | Figure 1 (1) |
| A | | |
| | Actuators: Unstable when removed, possible rotation of frame | Figure 4 (2), Figure 5 (2) |
| | System Unbalanced when rotor components are removed causing rotation | Figure 3 (5) |
| Fluids / Gases | Items: | Location |
| | X-Ray Tube Hydrocarbon Oil | Figure 3 (2) |
| | Generators Hydrocarbon Oil | Figure 3 (6) |
| | Overflow Tank Hydrocarbon Oil | Figure 3 (7) |
| Batteries | Type: | Location |
| To be Removed | | |
| Hazardous | Substances: | Location |
| | Printed Circuit Boards | Figure 1 (2), Figure 2 (1), Figure 4 (1), Figure 5 (1) |
| | Lead | Figure 3 (1),(3),(4) |
| | | |
| To be Removed | | |
| To be Removed | | |

Show locations of materials mentioned on the previous sheet. (Picture information)




Figure 1: Front View of Gantry with Covers on

Title: Recycle Passport Ingenuity CT Gantry

Recycling Passport Number: 459800122671 Rev: A




Figure 2: Rear View of Gantry with Covers on




Figure 3: Front View of Gantry with Front Cover Lifted

Title: Recycle Passport Ingenuity CT Gantry

Recycling Passport Number: 459800122671 Rev: A




Figure 4: Right Side View of Gantry with Cover Removed




Figure 5: Left Side View of Gantry with Cover Removed